

BIOS zeigt nur blinkenden Strich

Beitrag von „Wolfe“ vom 18. Januar 2021, 22:43

[Nightflyer](#)

Dortania: „BootProtect being left on "Bootstrap" has been known to cause Z87/Z97 motherboards to brick and can require the BIOS to be reflashed to fix“