


Umstieg von dGPU auf iGPU

Beitrag von „hackmac004“ vom 19. Januar 2021, 12:26

Möglicherweise helfen diese Einstellungen



The image shows a screenshot of a system configuration window, likely from a Mac OS. The window displays a list of device properties. The 'PciRoot(0x0)/Pci(0x2,0x0)' entry is highlighted in blue. The list includes various properties such as 'AAPL,ig-platform-id', 'device-id', 'framebuffer-patch-enable', 'enable-hdmi20', and 'framebuffer-unifiedmem', each with a corresponding data type and value.

Property	Type	Value
DeviceProperties	Dictionary	0 2 Schlüssel/Wert-Paare
Add	Dictionary	0 1 Schlüssel/Wert-Paare
PciRoot(0x0)/Pci(0x2,0x0)	Dictionary	0 3 Schlüssel/Wert-Paare
AAPL,ig-platform-id	Daten	0 4 Bytes: 07009B3E
device-id	Daten	0 4 Bytes: 9B3E0000
framebuffer-patch-enable	Daten	0 4 Bytes: 01000000
enable-hdmi20	Daten	0 4 Bytes: 01000000
framebuffer-unifiedmem	Daten	0 4 Bytes: 00000080
Delete	Dictionary	0 0 Schlüssel/Wert-Paare

und dieses boot arg `igfxonln=1`.