

Bluetooth Probleme mit Fenvi Karte und AirPods Pro

Beitrag von „Bob-Schmu“ vom 3. Februar 2021, 18:35

Da du ja den Ordner von [anonymous writer](#) benutzt für dein System, solltest du vielleicht mal schauen was für dein System relevant ist in dem Ordner ein paar aml's müssen raus.

Der AppleGraphicsDevicePolicy.kext ist das selbe wie

- `agdpmod=vit9696` disables check for `board-id` (or add `agdpmod` property to external GPU).
- `agdpmod=pikera` replaces `board-id` with `board-ix`

Patching AppleGraphicsDevicePolicy.kext

A long time ago (read seventeen months ago) I blogged about the changes in the AGDP (Apple Graphics Device Policy) and had to come up with a workaround for an issue in `AppleGraphicsDevicePolicy.kext` so that we could use a `MacPro6,1` `board-id/model` combination, without the usual hang with a black screen.

Today I like to present an alternative route for this and this time it is a patch that can be used with Clover's kext patching feature. Here it is:

```
<key>KextsToPatch</key>
<array>
  <dict>
    <key>Comment</key>
    <string>AppleGraphicsDevicePolicy (board-id) Patch (c) Pike R. Alt
    <key>Find</key>
    <data>
      Yn9kaQ==
    </data>
    <key>Name</key>
    <string>AppleGraphicsDevicePolicy</string>
    <key>Replace</key>
    <data>
      Yn9kaQ==
    </data>
  </dict>
</array>
```

Basically what we do is search for "board-id" and replace it with "board-ix" - or anything that we want to use instead. Please give it a go and let me know if it works for you.

Am besten ist du räumst da erst mal auf, weil entweder benutzt du eine `SSDT-UIAC.aml` oder `USBPorts.kext` aber nicht beides.