

Diskussionen zu: OPENCORE MIT X299: ASUS WS X299 SAGE/10G

Beitrag von „EvilGenius“ vom 22. Februar 2021, 18:07

According to Vit, deactivating the XhciPortLimit Quirk should help...

Do you have that with your board maybe still activated ?

With the C621 Chipset the problem also occurs but I tried 11.3 Beta 2 without patched USB ports...

Didnt had the time to try that afterwards... [juantrix](#)