

Lenovo Thinkpad T530

Beitrag von „Sascha_77“ vom 24. Februar 2021, 09:21

[antukst](#)

Yes but I'm talking about it because the mDP Port does not work with these dedicated GFX Card inside. You could switch it off in the BIOS. But the mDP is **hardwired** to this card. Its not possible to get out the HD4000 Videosignal through the Port. 5T33Z0 has an upgraded Model. There was an i5 inside before and than he upgraded to i7. The i5 has no dedicated GFX Card. Thats the reason because the mDP is working with the Intel HD on his machine.

I have the same model like you. The only way you could get the nVidia GFX Card (and therefore the mDP) working is to use 10.11. But its very buggy than and tricky. I think that it's not your aim. And who wants to use 10.11 these days?