

Dell XPS 17 9700

Beitrag von „RaymanOne“ vom 25. Februar 2021, 09:14

[Zitat von EdD1024](#)

Thanks, I figured it out by myself already. I just mapped the USB ports, trackpad and touchscreen both work. And even sleep without actually fixing it deliberately!

The last two issues I'm tackling right now is the missing sound (which alcid is it actually?) and the temporary black screen on the internal display. It is even not recognized to be internal. That's weird!

So I'm running latest Big Sur and OCv0.6.6 with a strange side effect it shows it's v0.6.3. Silly!

It's a config for 4K internal screen. Do you have it? I have and 0 problem with this config. Sound yes, it's a problem now. We should somehow report our id's to opencore devs.