

Hackintosh x79 Mojave does not shutdown completely

Beitrag von „Jono“ vom 28. Februar 2021, 00:30

You should have a look at USB port mapping.
Create a new USB Kext with Hackintool.

<https://youtu.be/y41MfHGoJ9c>