

# Brauche Hilfe, hänge bei ApplePS2Controller: Notification consumer published: ApplePS2Mouse + ACPI Errors

Beitrag von „hectorox“ vom 6. März 2021, 01:03

Ich habe es nun mit OpenCore 0.6.6 versucht, trotzdem bleibe ich noch beim touchpad stecken...

```
AppleACPICPU: Processor Id=1 LocalApicId=8 Enabled
AppleACPICPU: Processor Id=2 LocalApicId=2 Enabled
AppleACPICPU: Processor Id=3 LocalApicId=1 Enabled
AppleACPICPU: Processor Id=4 LocalApicId=3 Enabled
AppleACPICPU: Processor Id=5 LocalApicId=255 Disabled
AppleACPICPU: Processor Id=6 LocalApicId=255 Disabled
AppleACPICPU: Processor Id=7 LocalApicId=255 Disabled
AppleACPICPU: Processor Id=8 LocalApicId=255 Disabled
AppleACPICPU: Processor Id=9 LocalApicId=255 Disabled
AppleACPICPU: Processor Id=10 LocalApicId=255 Disabled
AppleACPICPU: Processor Id=11 LocalApicId=255 Disabled
AppleACPICPU: Processor Id=12 LocalApicId=255 Disabled
AppleACPICPU: Processor Id=13 LocalApicId=255 Disabled
AppleACPICPU: Processor Id=14 LocalApicId=255 Disabled
AppleACPICPU: Processor Id=15 LocalApicId=255 Disabled
AppleACPICPU: Processor Id=16 LocalApicId=255 Disabled
Darwin Image4 Validator Version 3.1.0: Thu Feb 18 22:59:40 PST 2021; root:AppleImage4-106.40.12-3660/AppleImage4/RELEASE_ARM_T804
 ACPI Warning: GPE_169 has no implementation[0017C: Version 0x20 Vectors 64:111]
 (2816933)/evrgnml(-465)
 ACPI Exception: RE_BAD_PARAMETER, Could not install PciConfig handler for Root Bridge PCI0 (2816933)/evrgnml(-340)
 ACPI: Executed 65 blocks of module-level executable AML code
 ACPI: sleep states S3 S4 S5
 HID: Legacy shia 2
 console relocated to 0xc0000000
 i PCI configuration end, bridges 4, devices 16 1
 Lilu user: 0 disabling ussr patcher on request!
 Couldn't alloc class "AppleIntelPchSerialBMC"
 _start(struct kmod_info, void) has been invoked
 [kern]::init [kern]::family_bests-1040.1" Jan 20 2021 23:50:09
 AppleIntelI2C-1::init I2CInfo: no I2C, validatedObj not returned Base00020c
 AppleIOWM assert failed: (0 != data) ReleaseMode file: /AppleInternal/BuildRoot/Library/Caches/com.apple.xbs/Sources/IOWMFamily/IOWMFamily-257.60.1/Common/IOWMController.cpp line: 5
 Debug: Publishing nub for slave device at address 0xc151touchpad probe
 AppleIntelI2CController-1::notificationPublishedHandler: getChannelNumber failed
 AppleIOWM assert failed: (0 != data) ReleaseMode file: /AppleInternal/BuildRoot/Library/Caches/com.apple.xbs/Sources/IOWMFamily/IOWMFamily-257.60.1/Common/IOWMController.cpp line: 5
 virtual IOWMController::CreateSubmissionQueue(int16_t, uint8_t):2087:50 Index=0 entrySize=64
 virtual IOWMController::CreateSubmissionQueue(int16_t, uint8_t):2087:50 Index=0 entrySize=64
 HID: Legacy shia 2
 apfs_module_start:2436: load: com.apple.filesystems.apfs, v1677.01.1, apfs-1677.01.1, 2021/01/24
 BuildIODeviceEntry enter
 AppleACPIDevice: start Entered
 BuildIODeviceEntry exit
 ApplePS2Controller: Notification consumer published: ApplePS2Controller
 ApplePS2Controller: Notification consumer published: ApplePS2Keyboard
 ApplePS2Controller: Notification consumer published: ApplePS2Mouse
 Debug: No response
 hello packet length fail: -6
 Debug: No response
 hello packet length fail: -6
 Debug: No response
 hello packet length fail: -6
 Debug: No response
 hello packet length fail: -6
 Debug: No response
 hello packet length fail: -6
 Debug: No response
 hello packet length fail: -6
 Debug: No response
 hello packet length fail: -6
 Debug: No response
 hello packet length fail: -6
 Debug: No response
 hello packet length fail: -6
 Debug: No response
 hello packet length fail: -6
 Debug: No response
 hello packet length fail: -6
 Error: Could not initialize ELN device.AppleIntelI2CController::_serviceMatchingTimeout: fTimeServiceMatching timed out, Notifications 0
```