

Suche Fix für Samsung PM981 M.2 SSD

Beitrag von „itisme“ vom 5. April 2021, 23:27

Laut Release-Notes der [NVMeFix Kext v1.0.6](#) könnte das Problem mit der Samsung PM981 m.2 SSD nun gefixt sein:

NVMeFix

0.0.0 pending security critical

NVMeFix is a set of patches for the Apple NVMe storage driver, IONVMeFamily. Its goal is to improve compatibility with non-Apple SSDs. It may be used both on Apple and non-Apple computers.

The following features are implemented:

- Autonomous Power State Transition to reduce idle power consumption of the controller.
- Host-driver active power state management.
- Workaround for timeout panics on certain controllers (VMware, Samsung PM981).

Kann das bereits jmd. bestätigen?