

Erledigt

AQUANTIA 10 Gigabit Lan Port "Tot"

Beitrag von „sunraid“ vom 1. September 2021, 21:12

[marthie_08](#)

Bei mir steckt diese Karte im Rechner und läuft ohne Patch...!

```
Aquantia AGC10G:  
Name: ethernet  
Typ: Ethernet-Controller  
PCI  
Hersteller-ID: 0x188a  
Geräte-ID: 0x8701  
Subsystem-Hersteller-ID: 0x1800  
Subsystem-ID: 0x7002  
Versions-ID: 0x0002  
Link-Breite: x4  
PCI-Name: eth1  
Modul-Name: AppleEthernetAquantiaAction.kext  
Ort: /System/Library/Extensions/IONetworkingFamily.kext/Contents/PlugIns/AppleEthernetAquantiaAction.kext  
Version: 1.0.0.4
```

Aus der FAQ:

[I upgraded macOS Big Sur to version 11.1, and my Solo10G stopped working.](#)

This update corrupts the network settings. To recover, you need to delete the network plists and recreate your network settings.

Launch Terminal and type the following:

```
sudo rm /Library/Preferences/SystemConfiguration/NetworkPreferences.plist  
sudo rm /Library/Preferences/SystemConfiguration/preferences.plist
```

Restart and recreate your network settings.

If that doesn't work, contact support@sonnettech.com. Be sure to save and send a System Report.

Dec-
15-
20