

Hänge beim USB booten fest

Beitrag von „OSX-Einsteiger“ vom 7. September 2021, 23:21

[SebiPlayz](#)

Das fehlt dir noch

Quirks	dict	
AppleCpuPmCfgLock	bool	false
AppleXcpmCfgLock	bool	false
AppleXcpmExtraMars	bool	false
AppleXcpmForceBoost	bool	false
CustomSMBIOSGuid	bool	false
DisableIoMapper	bool	false
DisableLinkeditJettison	bool	true
DisableRtcChecksum	bool	false
ExtendBTFeatureFlags	bool	false
ExternalDiskIcons	bool	false
ForceSecureBootScheme	bool	false
IncreasePciBarSize	bool	false
LapicKernelPanic	bool	false
LegacyCommpage	bool	false
PanicNoKextDump	bool	true
PowerTimeoutKernelPanic	bool	true
ProvideCurrentCpuInfo	bool	false
SetApfsTrimTimeout	integer	-1
ThirdPartyDrives	bool	false
XhciPortLimit	bool	true

Kann man hier nach lesen https://github.com/AMD-OSX/AMD_Vanilla/tree/master