

RX 6xxx(XT) Thread, Lieferbarkeit, Kompatibilität, Leistung

Beitrag von „CMMChris“ vom 19. September 2021, 11:57

Correct, Apple dropped native sensor readout starting from Vega20 because their own MPX module sensors deliver data via the SMC. Third party support has zero priority for Apple. Someone would need to develop a VirtualSMC or FakeSMC plugin to get readout of temps, fan speed and clock from non Apple GPUs again.