


In Arbeit

## Beelink U55 "Hack Mini" - inkl. EFI

Beitrag von „milantar“ vom 2. Oktober 2021, 16:41

Thanks for the quick reply. I made several tests and they all finish with stall after installing on SSD and reboot.

I;E; with Catalina, I succeeded with the boot from USB, I've been able to create a partition and to copy the files (install) but after the reboot, I fall in the following traces





which all end with a Kernel Panic

The same if I try to install other versions.

I was wondering if the problem could come from the BIOS version or settings. I have a S/N wich ends with PRO-V23. I actually have the factory version installed and I could update bios if necessary to EC\_VB1002 or EC\_VB1003.

I understood that the EFI with the config.plist and OC folder was already functional for any U55 but if it is not the case (and I have to update the plist.config can you share some guide or tools?. Any suggestion about the cause of the error I am facing?

Best Regards,

M.ilan