

HP EliteBook 840 G1 & OpenCore Catalina/Big Sur

Beitrag von „KlausFindus“ vom 7. Dezember 2021, 12:09

[Zitat von theCurseOfHackintosh](#)

Do you have latest bios on it? [Bios settings](#)? Latest opencore?

Yes i have the latest BIOS and checked also the [bios settings](#). Latest OpenCore (Used the EFI folder from Conn Post 966)

Still

1. Always a 5 sec delay before OpenCore UI gets responsive
2. Windows Boot not always possible -> reboot during startup
3. Windows Boot through BIOS is always working

Kind regards