

Huananzi x79 Dual CPU C602 Board & DDR3 RAM - Hackintosh Monterey 12.0/Windows 11 DevBeta mit OpenCore 0.7.0

Beitrag von „robcodemax“ vom 16. Dezember 2021, 08:30

[Zitat von haingo](#)

Hurray!!! Disabling DSDT and keeping the 3 SSDTs worked. I can boot into the recovery image now 😁

But I cannot control my USB mouse and keyboard. Let me try to use the usb mapping.

Create the UTBMap.kext using [USBToolbox app](#) and then replace the one that I have included. Also keep in mind you need the UTBDefault.kext and UTBToolbox.kext which I have already included in my EFI

Also we will try the Audio patch later if it doesn't work.

Also please give me the cpu bios name you can find this in the device manager in windows.

I think your cpu might be using SCK2 hence you got the error. I thought earlier that your PC might be using SCK0 and SCK1.

