

Huananzi x79 Dual CPU C602 Board & DDR3 RAM - Hackintosh Monterey 12.0/Windows 11 DevBeta mit OpenCore 0.7.0

Beitrag von „robcodemax“ vom 16. Dezember 2021, 09:12

[Zitat von haingo](#)

no you're not wrong. I used dual cpu setup actually. But I failed to boot into mac installer so i unplugged power cable of the second socket to try.

I cant boot into recovery image now. Very likely due to the usbttoolbox. I will try with your kexts. But even I can boot now, installing from recovery will take alot of time as my internet now is tereibly slow to download mac

Please let me know what is the bios name for second cpu then we can edit the DSDT accordingly.