

Huananzi x79 Dual CPU C602 Board & DDR3 RAM - Hackintosh Monterey 12.0/Windows 11 DevBeta mit OpenCore 0.7.0

Beitrag von „robcodemax“ vom 17. Dezember 2021, 08:39

[Zitat von haingo](#)

[robcodemax](#) you are just genius!!

Turning off XHCI handoff and EHCI handoff solved my problem 😊

I cannot boot with dual cpu though. So i will install with 1 cpu then

After installing we will try to enable dual CPU. But with the latest EFI you should be able to boot in with Dual CPU. No worries we will see. After installing we will try the Patched DSDT