

# Huananzi x79 Dual CPU C602 Board & DDR3 RAM - Hackintosh Monterey 12.0/Windows 11 DevBeta mit OpenCore 0.7.0

Beitrag von „haingo“ vom 17. Dezember 2021, 09:09

[Zitat von robcodemax](#)

After installing we will try to enable dual CPU. But with the latest EFI you should be able to boot in with Dual CPU. No worries we will see. After installing we will try the Patched DSDT

Actually, I have been using your latest EFI with USBMap.kext is the only modification to get USB keyboard and mouse work (along with turning off XHCI hand-off and EHCI hand-off). I mentioned above that I cannot boot with dual CPU. The screen gets stuck at

```
[ EB | #LOG:EXITBS:START ]
```

With single CPU, I can pass this point.