

Huananzi x79 Dual CPU C602 Board & DDR3 RAM - Hackintosh Monterey 12.0/Windows 11 DevBeta mit OpenCore 0.7.0

Beitrag von „robcodemax“ vom 18. Dezember 2021, 06:04

Now add SSDT-UNC, SSDT-EC-DESKTOP and disable SSDT-X79 and check if it's working

[Zitat von haingo](#)

I've added those SSDT files you mentioned but PM is still not working. I generated my SSDT-PM using ssdtpngen. Could you check if there is any issue with it?

