

HWC Frage zu: FUJITSU ESPRIMO D9010 (COMET LAKE)

Beitrag von „adres0k“ vom 22. Januar 2022, 11:31

Hi! Did you faced with "EB|LOG:EXITBS:START" error during initial OS installing? I tried solutions provided at "[Stuck on \[EB|#LOG:EXITBS:START\]](#)" but without any success. Hardware almost the same - 10900, Q470 - but HP vendor.

Code

```
1. 06:045 00:029 AAPL: #[EB.BST.FBS|KSSZ] 0
2. 06:076 00:030 AAPL: #[EB|SB:SBGMFNS] j185fap.im4m
3. 06:108 00:032 AAPL: #[EB|RH:PF] usr\standalone\OS.dmg.root_hash
4. 06:166 00:058 AAPL: #[EB|RH:MF] <"usr\standalone\OS.dmg.root_hash.j185fap.im4m">
5. 06:219 00:052 AAPL: #[EB.LD.LF|IN] 0 1 <"usr\standalone\OS.dmg.root_hash"> <"0">
6. 06:269      00:050      AAPL:      #[EB.LD.OFS|OPEN!]      Err(0xE)
   <"usr\standalone\OS.dmg.root_hash">
7. 06:304 00:034 AAPL: #[EB.RH.LRH|P!] Err(0xE) <- EB.LD.LF
8. 06:334 00:030 AAPL: #[EB.BST.FBS|!] Err(0xE) <- EB.RH.LRH
9. 06:364 00:030 AAPL: #[EB.B.WFDW|!WF] Err(0xE) 0
10. 06:395 00:030 AAPL: #[EB|LOG:DT] 2022-01-22T11:23:01
11. 06:427 00:032 AAPL: #[EB|LOG:EXITBS:START] 2022-01-22T11:23:01
```

Alles anzeigen