


[Sammelthread] MacOS Monterey 12.x DEV-Beta Erfahrungen

Beitrag von „fabiosun“ vom 18. März 2022, 13:46

[kaneske](#)

3) now is solved using a different framebuffer in Device Properties (Carswell)



Key	Data Type	Value
ATIName	String	ATI_Carswell
ATIRevision	Data	00000007
ATIChip	String	ATI_CarswellPine1
Model	String	AMD Radeon RX 6000XT
Name	Data	AMDGPU00000