

Die super OOB Bluetooth Karte macht mehr Probleme als Intel. Bitte um Hilfe.

Beitrag von „Judzhin“ vom 25. Mai 2022, 22:04

```
C:\Users\Eugen\AppData\Local\Temp\Rar$EXa5172.46889\dist\Windows.exe
#####
#                               Port Discovery                               #
#####

Intel(R) USB 3.1 eXtensible-Hostcontroller - 1.10 (Microsoft) | USB 3.0
Port 1 | USB 2.0 | USB 3 Type A (guessed)
Port 2 | USB 2.0 | USB 3 Type A (guessed)
  - USB2.0 Hub - operating at USB 2.0
  - BRCM20702 Hub - operating at USB 1.1
  - Bluetooth USB Host Controller - operating at USB 1.1
  - NZXT USB Device - operating at USB 1.1
Port 3 | USB 2.0 | USB 3 Type A (guessed)
Port 4 | USB 2.0 | USB 3 Type A (guessed)
Port 5 | USB 2.0 | USB 3 Type A (guessed)
Port 6 | USB 2.0 | Type A (guessed)
Port 7 | USB 2.0 | Type C - with switch (guessed)
Port 8 | USB 2.0 | USB 3 Type A (guessed)
Port 9 | USB 2.0 | Type C - with switch (guessed)
Port 10 | USB 2.0 | USB 3 Type A (guessed)
  - USB Receiver - operating at USB 1.1
Port 11 | USB 2.0 | Type A (guessed)
Port 12 | USB 2.0 | Type A (guessed)
Port 13 | USB 2.0 | Type A (guessed)
  - ITE Device - operating at USB 1.1
Port 14 | USB 2.0 | Type A (guessed)
  - Intel(R) Wireless Bluetooth(R) - operating at USB 1.1
Port 15 | USB 2.0 | Internal (guessed)
Port 16 | USB 2.0 | Internal (guessed)
Port 17 | USB 3.0 | USB 3 Type A (guessed)
Port 18 | USB 3.0 | USB 3 Type A (guessed)
Port 19 | USB 3.0 | USB 3 Type A (guessed)
Port 20 | USB 3.0 | USB 3 Type A (guessed)
Port 21 | USB 3.0 | USB 3 Type A (guessed)
Port 22 | USB 3.0 | Type C - with switch (guessed)
Port 23 | USB 3.0 | Internal (guessed)
Port 24 | USB 3.0 | USB 3 Type A (guessed)
Port 25 | USB 3.0 | Internal (guessed)
Port 26 | USB 3.0 | USB 3 Type A (guessed)

B. Back

Waiting 5 seconds: b
```

ok probiere ich mal jetzt.