

Anfrage zu HWC: DELL XPS 13 9343

Beitrag von „Basti Wolf“ vom 8. Juli 2022, 08:54

Sorry for the late reply. At the moment I have a lot to do and the device is not there. But I'll have it delivered to me tomorrow so I can help better.

First we will check the [bios settings](#) and the bios version again. If everything is correct, all unnecessary things in the EFI are first deactivated. But I find that a bit funny, since there are hardly any differences apart from the DW1820. But the 1820 needs exactly the same kexts as the 1560.

More then tomorrow.