

Ryzentosh - Auros B550i PRO AX - "3,6GHz Unbekannt" fix ?

Beitrag von „fabiosun“ vom 8. August 2022, 14:24

[user1](#) Which version of OpenCore are you using?

You have some error in your config

If you use in PlatformInfo Automatic value on Yes

you don't need of DataHub and SMBIOS options (these are useful if you have automatic on NO and then it is mandatory to fill all that config.plist part

To back to your question, if you use latest OpenCore you have to add a driver on Uefi/drivers section to see reset Nvram button