

Ryzentosh - Auros B550i PRO AX - "3,6GHz Unbekannt" fix ?

Beitrag von „user1_“ vom 8. August 2022, 14:58

[fabiosun](#)

I use OC 0.8.3 nvramreset is now shown, thanks.

I set platform info to false, processortype to 3841 (I also tested 0) and deleted revcpu/ revcpu name.

unfortunately the cpu is still not recognized, even after a nvram reset