

Anfrage aus dem HWC - Dell XPS 13 9343

Beitrag von „Basti Wolf“ vom 3. November 2022, 15:42

There was a mistake inside the config.plist. Now I've fixed it and you can try it again. Please create new Serial numbers as well.

Please also fill in your spec in your profil especial for the cpu. 😊