

Hackintosh stürzt nach kurzer zeit ab

Beitrag von „ozw00d“ vom 18. November 2022, 08:19

[Fynn](#) it seems your usb Ports aren't correctly mapped.

read about the ssdt usb solution. It works much finer than the old usbkext method.

i have seen this also with my board and many others.

It works also with the kext, but apple is working on the way how usb is working on a Mac on each new version.

I don't really understand why apple is changing everytime things on usb.

could you please attach an ioreg dump and your usbkext?

I could bet that the problem is an usb related thingy.