

OpenCore Sammelthread (Hilfe und Diskussion)

Beitrag von „LetsGo“ vom 21. November 2022, 19:52

Ich glaube, wenn man unter den 15Ports/Controller ist, kann man sich das Mapping sparen. Wobei man bedenken muss, das manche Ports physisch nicht vorhanden sind, obwohl sie im ACPI hinterlegt sind.

Musste bei mir auch 11 Ports von 26 streichen, obwohl es die so gar nicht gibt. Aber der XHCI Controller kann halt 26 Ports händeln und die sind im ACPI auch hinterlegt. In meinem Fall halt.



The screenshot shows a system utility window with a dark background. At the top, it displays 'Type: XHCI' and 'ID: 0x18' for the 'Canon Labs PCI USB 3.1 XHCI Host Controller'. Below this, there is a section titled 'USB Ports' which contains a table listing 26 individual ports. Each row in the table includes the port type (all are XHCI), a Name (e.g., H001), a Location ID (e.g., 0x14010001), a Port number (e.g., 0x01), a Connector type (e.g., USB2), a File Speed (e.g., 1), and a Device status (e.g., Unplugged).

Type	Name	Location ID	Port	Connector	File Speed	Device
XHCI	H001	0x14010001	0x01	USB2	1	Unplugged
XHCI	H002	0x14010002	0x02	USB2	1	Unplugged
XHCI	H003	0x14010003	0x03	USB2	1	Unplugged
XHCI	H004	0x14010004	0x04	USB2	1	Unplugged
XHCI	H005	0x14010005	0x05	USB2	1	Unplugged
XHCI	H006	0x14010006	0x06	USB2	1	Unplugged
XHCI	H007	0x14010007	0x07	USB2	1	Unplugged
XHCI	H008	0x14010008	0x08	USB2	1	Unplugged
XHCI	H009	0x14010009	0x09	USB2	1	Unplugged
XHCI	H010	0x1401000A	0x0A	USB2	1	Unplugged
XHCI	H011	0x1401000B	0x0B	USB2	1	Unplugged
XHCI	H012	0x1401000C	0x0C	USB2	1	Unplugged
XHCI	H013	0x1401000D	0x0D	USB2	1	Unplugged
XHCI	H014	0x1401000E	0x0E	USB2	1	Unplugged
XHCI	H015	0x1401000F	0x0F	USB2	1	Unplugged
XHCI	H016	0x14010010	0x10	USB2	1	Unplugged
XHCI	H017	0x14010011	0x11	USB2	1	Unplugged
XHCI	H018	0x14010012	0x12	USB2	1	Unplugged
XHCI	H019	0x14010013	0x13	USB2	1	Unplugged
XHCI	H020	0x14010014	0x14	USB2	1	Unplugged
XHCI	H021	0x14010015	0x15	USB2	1	Unplugged
XHCI	H022	0x14010016	0x16	USB2	1	Unplugged
XHCI	H023	0x14010017	0x17	USB2	1	Unplugged
XHCI	H024	0x14010018	0x18	USB2	1	Unplugged
XHCI	H025	0x14010019	0x19	USB2	1	Unplugged
XHCI	H026	0x1401001A	0x1A	USB2	1	Unplugged