

# x299 pro/se freeze in Monterey or Ventura

**Beitrag von „startergo“ vom 29. Dezember 2022, 14:34**

I have replaced the MOBO with a similar one:

[x299 SAGE](#) (no 10G ethernet) and there are no more freezes so far. I have noticed that the previous board had bad CMOS battery (around 0.3VDC), but I don't think that would have caused such issues. Most probably the board itself.