

CPU AMD A10 5800k | MB Asrock FM2A88X Extreme4+ | GPU AMD Radeon HD 7660D oder NVIDIA Geforce GTX 750 Ti

Beitrag von „BUSTER“ vom 9. Januar 2023, 20:52

[Zitat von fabiosun](#)

If you are using an usb pen to boot, try to use another usb port of your motherboard

If same problem you have to try to map your usb port

after try boot from other USB Ports, the fourth attempt worked, ventura is currently being installed 😊

I will continue to report

thanks a lot guys

EDIT 1:

Ventura should actually be installed, but when booting it comes to a reboot, [fabiosun](#) are still missing important kexts?

EDIT 2: Upload EFI, Debug On

cYa BUSTER