

High Sierra 10.13.6 - Z68X-UD3H-B3 (UEFI BIOS - U1n) - i7 2600K - GTX 570

Beitrag von „Bob-Schmu“ vom 30. April 2024, 13:43

Hattest auch mal eine älter Kext Version probiert.

Changelog

- Version 2.3.0 (2020-08-14)
 - Reworked medium section and EEE support to resolve problems with connection establishment and stability
 - Added option to supply a fallback MAC.
 - Updated Linux sources to 8.047.04 and added support for new family members
 - Requires 10.14 or newer.
- Version 2.2.2 (2018-01-21)
 - Force ASPM state to disabled/enabled according to the config parameter setting.
 - Requires 10.12 or newer.
- Version 2.2.1 (2016-03-12):
 - Updated underlying linux sources from Realtek to 8.041.00.
 - Added support for RTL8111H.
 - Implemented Apple's polled receive driver model (RXPOLL).
 - Requires 10.11 or newer. Support for older versions of OS X has been dropped.