

# Ventura Ryzen 5

Beitrag von „fabiosun“ vom 29. Juli 2024, 08:10

[wu ming](#)

if motherboard you have in your signature is right

you have this ethernet:

Intel® I211-AT, 1 x Gigabit LAN Controller(s)

so your ethernet kext is wrong

you can find an updated kext for it AppleIb modified by Lorys89 and mbarbierato on their github

and it works well for AMD motherboard

check you original working EFI

you used Smalltree kext till Big Sur (see max kernel value) then you used AppleIGB kext

then i would like to ask:

Do you know the meaning for amd desktop (without a supported IGPU) of this two patches:



I have asked and the best answer was

if you do not need they are not harmful...

this answer is it enough for you to use them on your system?

IMHO No 😊

[EFI\\_WU\\_Ming.zip](#)

if you like try this EFI based from the one you posted in first post

If it hangs take a photo or a video where it happens