


Anleitung für Broadcom-WLAN-Patch unter macOS Sonoma

Beitrag von „max.1974“ vom 9. Oktober 2024, 16:05



[HD 620 intel HDMI LCD Fix.plist.zip](#)

```
enable-max-pixel-clock-override <> data <> 01000000
```

```
framebuffer-stolenmem <> data <> 00003001
```

```
framebuffer-unifiedmem <> data <> 00000080
```