

Matebook X Installation USB 3 Kompatibilität und mehr ... ??

Beitrag von „waldfee123“ vom 15. November 2024, 15:06

Hab es jetzt installiert bekommen ... Aber schon ab Mitte der Installation finf plötzlich das Bild durchgehend das blinken an ... Ich kann ganz normal steuern und schreiben , nur das Bild blinkt während der Installation und auch danach ... War aber erst kurz bevor das Install Menü kam ...

Was kann ich dagegen tun ? Das wäre erstmal das schlimmste To do ...

Hier meckert er auch was an ... Danach blinkt es ...

```
AppleKeyStore:12192:144: operation failed (url: ? ret: 0000020, -1)
[[GPU] Hash data from MC never returned, status = 1, doing retry #89
[[GPU] Begin Gfx Firmware load process
[[GPU] Forcewake Multithread = 0x000002
[[GPU] CWF ID (0x000) = 0x00000000
[[GPU] GT_HASHID_538105 = 0x00000000
[[GPU] Doing retry #89
[[GPU] Hash data from MC never returned, status = 1, doing retry #89
[[GPU] Begin Gfx Firmware load process
[[GPU] Forcewake Multithread = 0x000002
[[GPU] CWF ID (0x000) = 0x00000000
[[GPU] GT_HASHID_538105 = 0x00000000
[[GPU] Doing retry #89
[[GPU] Hash data from MC never returned, status = 1, doing retry #89
[[GPU] Begin Gfx Firmware load process
[[GPU] Forcewake Multithread = 0x000002
[[GPU] CWF ID (0x000) = 0x00000000
[[GPU] GT_HASHID_538105 = 0x00000000
[[GPU] Doing retry #89
[[GPU] Failed to initialize graphics firmware.
[[GPU] Request to send host -> Gfx Firmware message when the firmware channel is not active
[[GPU] Failed to send wait-for-firmware request to firmware
near succeeded 0x011, 0x0a, 0x0a)
AppleKeyStore:12192:148: unexpected session uid: -1 requested by: bluestosh (148)
AppleKeyStore:12192:148: operation failed (url: ? ret: 0000020, -1)
AppleKeyStore:12192:148: operation failed (url: ? ret: 0000020, -1)
[[Comms] [time] 0-20, line 0, file 1
[[Comms] [time] 0-20, line 0, file 1
AppleKeyStore:12192:148: unexpected session uid: -1 requested by: bluestosh
```