

# Instantwake-Problem am Laptop, aber nur im Netzbetrieb

Beitrag von „iPhoneTruth“ vom 24. Januar 2025, 10:47

Ich bin ein bisschen weiter. Bisher hatte ich das Hackbook an der obersten USB-C Buchse aufgeladen. Das ging zwar, doch hat er den Anschluß zugleich als USB-Gerät gewertet, so daß dies dann den Instantwake verursacht hat.

Wenn ich nun einen der beiden unteren USB-C Anschlüsse für das Aufladen mit dem Netzteil verwende, hat er keine Instantwakes mehr. Allerdings einige Wakeups schon. Das sieht dann folgendermaßen aus:

```
2025-01-23 13:42:10.308825+0100 localhost kernel[0]: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: PWRB XHC (User)
2025-01-23 13:42:10.308829+0100 localhost kernel[0]: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: PWRB XHC (User)
2025-01-23 16:48:04.514018+0100 localhost kernel[0]: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: RTC0 XHC (Alarm)
2025-01-23 16:48:04.514023+0100 localhost kernel[0]: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: RTC0 XHC (Alarm)
2025-01-23 17:01:38.174174+0100 localhost kernel[0]: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: XHC
2025-01-23 17:01:38.174178+0100 localhost kernel[0]: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: XHC
2025-01-23 21:23:16.376477+0100 localhost kernel[0]: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: RTC0 XHC (Alarm)
2025-01-23 21:23:16.376482+0100 localhost kernel[0]: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: RTC0 XHC (Alarm)
2025-01-23 21:45:30.607804+0100 localhost kernel[0]: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: RTC0 XHC (Alarm)
2025-01-23 21:45:30.607809+0100 localhost kernel[0]: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: RTC0 XHC (Alarm)
2025-01-24 04:03:23.312062+0100 localhost kernel[0]: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: RTC0 XHC (Alarm)
2025-01-24 04:03:23.312066+0100 localhost kernel[0]: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: RTC0 XHC (Alarm)
2025-01-24 05:58:55.725390+0100 localhost kernel[0]: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: RTC0 XHC (Alarm)
2025-01-24 05:58:55.725394+0100 localhost kernel[0]: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: RTC0 XHC (Alarm)
2025-01-24 09:02:13.099090+0100 localhost kernel[0]: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: XHC
2025-01-24 09:02:13.099094+0100 localhost kernel[0]: (AppleACPIPlatform) AppleACPIPlatformPower Wake reason: XHC
```

XHC steht wohl für USB,

PWRB für Powerbutton,

und für RTC0 müßte ich wohl das hier noch einmal durcharbeiten [RTCMemoryFixup.kext](https://www.hackintosh-forum.de/forum/thread/60129-instantwake-problem-am-laptop-aber-nur-im-netzbetrieb/?postID=799097#post799097) oder?