

Bluetooth/Airplay über Fenvi FV-T919 will nicht.

Beitrag von „Kaffebecher“ vom 4. Februar 2025, 11:20

Hm, hab jetzt mehrfach noch einmal mit dem <https://github.com/corpnewt/USBMap> Guide eine neue USB Map erstellt, Dummy USB Kext geladen, dann gemapped und alle Connector Typen gemacht, Dummy Kext ausgetauscht mit der erstellten USB Map, reboot -> Es will immer noch nicht. Wirklich komplett ratlos an dieser Stelle 😞


Wohl gemerkt, ich hab wirklich nicht einen Peil was ich hier mache. Ich folge nur blinds irgendwelchen Guides, in der Annahme dass mich das irgendwo hinbringt.

e: Grad mal in Windows 10 die Bluetooth und WLAN Treiber für die Fenvi T919 installiert, da funktionierst - das schliesst schon einmal aus dass Bluetooth gar nicht auf der Karte funktioniert.

e2: Okay got it fixed! Weil dieser BCM_4350C2 Chipsatz doch wohl was spezielleres ist, hab ich mal das <https://github.com/acidanthera/BrcmPatchRAM> BluetoothFixup Kext hinzugefügt. Jetzt geht auch Bluetooth und somit auch Airdrop.

Vielen Dank noch einmal für den Hinweis auf den Chipsatz.

hackintosh-forum.de/attachment/220909/



```

# Discover USB Ports #
#####

----- XHCI@14 Controller -----
1. HS01 | AppleUSB20XHCIPort | 1 (01000000) | 14100000 | Type 0
  Rot USB 2.0 (from ioreg)
2. HS03 | AppleUSB20XHCIPort | 3 (03000000) | 14200000 | Type 0
  Blau USB 2.0 L (from ioreg)
3. HS04 | AppleUSB20XHCIPort | 4 (04000000) | 14300000 | Type 0
  Blau USB 2.0 R (from ioreg)
4. HS06 | AppleUSB20XHCIPort | 6 (06000000) | 14400000 | Type 0
  4er USB2.0 (from ioreg)
  - USB2.0 Hub
    - AppleUSB20Hub
      - MX518 Gaming Mouse
      - PCR
      - USB2.1 Hub
        - AppleUSB20Hub
          - LG Monitor Controls
          - Keyboard Hub
            - AppleUSB20KeyboardHub
              - Apple Keyboard
            - AppleUSB20Hub
              - UltraLite-mk5
        - AppleUSB20Hub
          - Bios USB 2.0 (from ioreg)
        - AppleUSB20Hub
          - Top USB R (from ioreg)
        - AppleUSB20Hub
          - Top USB L (from ioreg)
        - AppleUSB20Hub
          - HS11 | AppleUSB20XHCIPort | 11 (0b000000) | 14800000 | Type 255
            InternalUSB-Bluetooth (from ioreg)
            - USB2.0 Hub
              - AppleUSB20InternalHub
                - BRCM20702 Hub
                  - AppleUSB20Hub
                    - Bluetooth USB Host Controller
              - AppleUSB20Hub
                - Bluetooth USB Host Controller
            - AppleUSB20Hub
              - Rot USB 3.0 (from ioreg)
            - AppleUSB20Hub
              - USB-C (from ioreg)
            - AppleUSB20Hub
              - Blau USB 3.0 L (from ioreg)
            - AppleUSB20Hub
              - Blau USB 3.0 R (from ioreg)
            - AppleUSB20Hub
              - Top USB 3.0 R (from ioreg)
            - AppleUSB20Hub
              - Top USB 3.0 L (from ioreg)
          - AppleUSB20Hub
            - Rot USB 3.0 (from ioreg)
          - AppleUSB20Hub
            - USB-C (from ioreg)
          - AppleUSB20Hub
            - Blau USB 3.0 L (from ioreg)
          - AppleUSB20Hub
            - Blau USB 3.0 R (from ioreg)
          - AppleUSB20Hub
            - Top USB 3.0 R (from ioreg)
          - AppleUSB20Hub
            - Top USB 3.0 L (from ioreg)

Populated:
pci1002,73a4: 0, XHCI: 2

Press Q then [enter] to stop

```