

kein Audiogerät nach Installation - OptiPlex 7070 MFF

Beitrag von „Hecatomb“ vom 18. April 2025, 23:26

[Zitat von mr.flow3](#)

Es ist eine PM981a.

SSD/Storage Options that are NOT supported:

- Samsung PM981 and PM991 (commonly found in OEM systems like laptops)
 - Even if PM981 has been fixed with [NVMeFix](#) [\(opens new window\)](#) version 1.0.2 there is still plenty of kernel panics issues
- Micron 2200S
 - Many users have report boot issues with this drive
- SK Hynix PC711
 - The proprietary Hynix NVMe controller on this drive is not supported at all, and it will not boot with macOS

<https://dortania.github.io/Ant...Buyers-Guide/Storage.html>

Keine Ahnung ob deine auch dazu zählt.