

Erledigt

Installationsprobleme Gigabyte GA-EX58-UD5

Beitrag von „thommel“ vom 21. Oktober 2013, 19:42

[TuRock,](#)

alles installiert, alle Einstellungen ausprobiert, Ton kaum zu hören.

Thomas

Edit: Dev. ID ist aber richtig

Ven ID	Vendor	Dev ID	Device	Class	Subclass
8086	Intel Corporation	3a30	82801JI (ICH10 Family) SMBus Controller	Serial bus controller	SMBus
8086	Intel Corporation	2681	631xESB/632xESB SATA AHCI Controller	Mass storage controller	SATA controller
8086	Intel Corporation	3a18	82801JIB (ICH10) LPC Interface Controller	Bridge	ISA bridge
104c	Texas Instruments	8024	TSB43AB23 IEEE-1394a-2000 Controller (PHY/Link)	Serial bus controller	FireWire (IEEE 1394)
8086	Intel Corporation	244e	82801 PCI Bridge	Bridge	PCI bridge
8086	Intel Corporation	3a3a	82801JI (ICH10 Family) USB2 EHCI Controller #1	Serial bus controller	USB Controller
8086	Intel Corporation	3a36	82801JI (ICH10 Family) USB UHCI Controller #3	Serial bus controller	USB Controller
8086	Intel Corporation	3a35	82801JI (ICH10 Family) USB UHCI Controller #2	Serial bus controller	USB Controller
8086	Intel Corporation	3a34	82801JI (ICH10 Family) USB UHCI Controller #1	Serial bus controller	USB Controller
10ec	Realtek Semiconduct...	8168	RTL8111/8168B PCI Express Gigabit Ethernet controller	Network controller	Ethernet controller
8086	Intel Corporation	3a4a	82801JI (ICH10 Family) PCI Express Root Port 6	Bridge	PCI bridge
10ec	Realtek Semiconduct...	8168	RTL8111/8168B PCI Express Gigabit Ethernet controller	Network controller	Ethernet controller
8086	Intel Corporation	3a48	82801JI (ICH10 Family) PCI Express Root Port 5	Bridge	PCI bridge
197b	JMicron Technology C...	2363	JMB362/JMB363 Serial ATA Controller	Mass storage controller	IDE interface
8086	Intel Corporation	3a42	82801JI (ICH10 Family) PCI Express Port 2	Bridge	PCI bridge
8086	Intel Corporation	3a40	82801JI (ICH10 Family) PCI Express Root Port 1	Bridge	PCI bridge
8086	Intel Corporation	3a3e	82801JI (ICH10 Family) HD Audio Controller	Multimedia controller	Audio device
8086	Intel Corporation	3a3c	82801JI (ICH10 Family) USB2 EHCI Controller #2	Serial bus controller	USB Controller
8086	Intel Corporation	3a39	82801JI (ICH10 Family) USB UHCI Controller #6	Serial bus controller	USB Controller
8086	Intel Corporation	3a38	82801JI (ICH10 Family) USB UHCI Controller #5	Serial bus controller	USB Controller
8086	Intel Corporation	3a37	82801JI (ICH10 Family) USB UHCI Controller #4	Serial bus controller	USB Controller
8086	Intel Corporation	342f	5520/5500/X58 Trusted Execution Technology Registers	Generic system perip...	PIC
8086	Intel Corporation	3423	5520/5500/X58 I/O Hub Control Status and RAS Registers	Generic system perip...	PIC
8086	Intel Corporation	3422	5520/5500/X58 I/O Hub GPIO and Scratch Pad Registers	Generic system perip...	PIC
8086	Intel Corporation	342e	5520/5500/X58 I/O Hub System Management Registers	Generic system perip...	PIC
8086	Intel Corporation	342d	5520/5500/X58 I/O Hub I/OxAPIC Interrupt Controller	Generic system perip...	PIC
8086	Intel Corporation	3428	5520/5500 Routing & Protocol Layer Register Port 1	Generic system perip...	PIC
8086	Intel Corporation	3427	5520/5500 Physical and Link Layer Registers Port 1	Generic system perip...	PIC
8086	Intel Corporation	3426	5520/5500/X58 Routing and Protocol Layer Registers Port 0	Generic system perip...	PIC
8086	Intel Corporation	3425	5520/5500/X58 Physical and Link Layer Registers Port 0	Generic system perip...	PIC
1002	ATI Technologies Inc	aa58	Juniper HDMI Audio [Radeon HD 5700 Series]	Multimedia controller	Audio device
1002	ATI Technologies Inc	68be	Juniper [Radeon HD 5750 Series]	Display controller	VGA compatible cont...
8086	Intel Corporation	340e	5520/5500/X58 I/O Hub PCI Express Root Port 7	Bridge	PCI bridge
8086	Intel Corporation	3405	5520/5500/X58 I/O Hub to ESI Port	Bridge	Host bridge