

Erledigt

Braodcom 4306 PCI Wifi

Beitrag von „memosi“ vom 22. April 2014, 19:50

Habe ohne Probleme Mac OS X 10.9.2 installiert, alles funktioniert bis auf Braodcom 4306 PCI wifi karte.

kleine log

Beitrag von „TuRock“ vom 22. April 2014, 20:03

Deine ID´s =

Device id: 0x4307

Vendor id: 0x14E4

Versuch mal diesen kext s.Anhang !

Beitrag von „memosi“ vom 22. April 2014, 21:34

danke für deine Antwort. wo kommt die

Code

1. Deine ID´s =
2. Device id: 0x4307
3. Vendor id: 0x14E4

info.plist?

Code

1. <string>pci106b,4e</string>

2. <string>pci14e4,4311</string>
3. <string>pci14e4,4312</string>
4. <string>pci14e4,4313</string>
5. <string>pci14e4,4318</string>
6. <string>pci14e4,4319</string>
7. <string>pci14e4,4320</string>
8. <string>pci14e4,4307</string>
9. <string>pci14e4,4320</string>
10. <string>pci14e4,4324</string>
11. <string>pci14e4,4325</string>
12. <string>pci14e4,4328</string>
13. <string>pci14e4,432c</string>
14. <string>pci14e4,432d</string>

Alles anzeigen

Beitrag von „ProfA12345“ vom 22. April 2014, 21:37

Die ist von TuRock, scheinbar, schon eingetragen. Siehe: <string>pci14e4,4307</string>

Beitrag von „memosi“ vom 22. April 2014, 22:01

lspci -nn

Zitat

```
00:00.0 Host bridge [0600]: Intel Corporation 82X38/X48 Express DRAM Controller  
[8086:29e0] (rev 01)
```

```
00:01.0 PCI bridge [0604]: Intel Corporation 82X38/X48 Express Host-Primary PCI  
Express Bridge [8086:29e1] (rev 01)
```

00:1a.0 USB controller [0c03]: Intel Corporation 82801I (ICH9 Family) USB UHCI Controller #4 [8086:2937] (rev 02)

00:1a.1 USB controller [0c03]: Intel Corporation 82801I (ICH9 Family) USB UHCI Controller #5 [8086:2938] (rev 02)

00:1a.2 USB controller [0c03]: Intel Corporation 82801I (ICH9 Family) USB UHCI Controller #6 [8086:2939] (rev 02)

00:1a.7 USB controller [0c03]: Intel Corporation 82801I (ICH9 Family) USB2 EHCI Controller #2 [8086:293c] (rev 02)

00:1b.0 Audio device [0403]: Intel Corporation 82801I (ICH9 Family) HD Audio Controller [8086:293e] (rev 02)

00:1c.0 PCI bridge [0604]: Intel Corporation 82801I (ICH9 Family) PCI Express Port 1 [8086:2940] (rev 02)

00:1c.2 PCI bridge [0604]: Intel Corporation 82801I (ICH9 Family) PCI Express Port 3 [8086:2944] (rev 02)

00:1c.4 PCI bridge [0604]: Intel Corporation 82801I (ICH9 Family) PCI Express Port 5 [8086:2948] (rev 02)

00:1d.0 USB controller [0c03]: Intel Corporation 82801I (ICH9 Family) USB UHCI Controller #1 [8086:2934] (rev 02)

00:1d.1 USB controller [0c03]: Intel Corporation 82801I (ICH9 Family) USB UHCI Controller #2 [8086:2935] (rev 02)

00:1d.2 USB controller [0c03]: Intel Corporation 82801I (ICH9 Family) USB UHCI Controller #3 [8086:2936] (rev 02)

00:1d.7 USB controller [0c03]: Intel Corporation 82801I (ICH9 Family) USB2 EHCI Controller #1 [8086:293a] (rev 02)

00:1e.0 PCI bridge [0604]: Intel Corporation 82801 PCI Bridge [8086:244e] (rev 92)

00:1f.0 ISA bridge [0601]: Intel Corporation 82801IR (ICH9R) LPC Interface Controller [8086:2916] (rev 02)

00:1f.2 SATA controller [0106]: Intel Corporation 82801IR/IO/IH (ICH9R/DO/DH) 6 port SATA Controller [AHCI mode] [8086:2922] (rev 02)

00:1f.3 SMBus [0c05]: Intel Corporation 82801I (ICH9 Family) SMBus Controller [8086:2930] (rev 02)

01:00.0 VGA compatible controller [0300]: NVIDIA Corporation G84 [GeForce 8600 GT] [10de:0402] (rev a1)

02:00.0 IDE interface [0101]: JMicron Technology Corp. JMB368 IDE controller [197b:2368]

03:00.0 Ethernet controller [0200]: Marvell Technology Group Ltd. 88E8056 PCI-E Gigabit Ethernet Controller [11ab:4364] (rev 12)

05:02.0 Network controller [0280]: Broadcom Corporation BCM4306 802.11b/g Wireless LAN Controller [14e4:4320] (rev 03)

05:03.0 FireWire (IEEE 1394) [0c00]: VIA Technologies, Inc. VT6306/7/8 [Fire II(M)] IEEE 1394 OHCI Controller [1106:3044] (rev c0)

Alles anzeigen

Beitrag von „TuRock“ vom 22. April 2014, 22:14

Wird die Karte erkannt oder nicht ?!

Beitrag von „memosi“ vom 22. April 2014, 22:22

Ich sehe keine wifi ich kann nur via ethernet (LAN) inet nutzen Airport zeigt mir auch nur lan keine wlan.

Beitrag von „TuRock“ vom 22. April 2014, 22:32

versuche mal die hier..

Beitrag von „memosi“ vom 23. April 2014, 00:34

nein läuft immer noch nicht. habe alles mögliche versucht.

Beitrag von „TuRock“ vom 23. April 2014, 21:01

Kannst du bitte schauen was für ID´s die Karte hat, ich bin mir mit Device id: 0x4307 nicht sicher ... 😞

Beitrag von „memosi“ vom 24. April 2014, 16:20

laut lspci -nn

Device id: 0x4320

Zitat

```
05:02.0 Network controller [0280]: Broadcom Corporation BCM4306 802.11b/g  
Wireless LAN Controller [14e4:4320] (rev 03)
```

Beitrag von „TuRock“ vom 24. April 2014, 17:21

Schau mal ob die hier funktioniert !

Beitrag von „memosi“ vom 24. April 2014, 21:55

vielen lieben dank, jetzt funktioniert es.

habe noch ein problem iMessage funktioniert nicht, FaceTime, App Store alles geht.

Beitrag von „ProfA12345“ vom 24. April 2014, 21:57

Zu dem Thema gibt es über 3000.Threads. Siehe:
<https://www.google.de/search?q...forum.de&biw=1920&bih=917>

Beitrag von „memosi“ vom 24. April 2014, 22:44

Kreditkarte hinzufügen danach funktioniert auch iMessage. Danke für Hilfe.