

Erledigt

## USB 2.0 USB 3.0 EL CAPITAN 10.11.4

### Beitrag von „Sofista“ vom 23. April 2016, 05:16

how to use and install the kext BInjectAll? use the x el capitán 10.11.4 with Clover UEFI ... only two USB 2.0 ports are not enabled ... where low this kextUSBInjectall? ... And how to install this kextUSBInjectall? kext that enables all USB 2.0 ports and USB 3.0?

---

### Beitrag von „griven“ vom 26. April 2016, 22:37

If some ports are missing/not enabled this is mainly because of apples port Restrictions. To get rid of this restrictions you have to edit AppleUSBEHCIPCI.kext which can be found inside IOUSBHostFamily.kext. Just open it's Info.plist and navigate to your chosen machine type (SMBIOS) under IOKitPersonalities (in my case the model ist iMAC 13.1) and you'll find something similar to this

Code

1. <key>iMac13,3-EHC1</key>
2. <dict>
3. <key>CFBundleIdentifier</key>
4. <string>com.apple.driver.AppleUSBMergeNub</string>
5. <key>IOClass</key>
6. <string>AppleUSBMergeNub</string>
7. <key>IONameMatch</key>
8. <string>EHC1</string>
9. <key>IOProviderClass</key>
10. <string>AppleUSBEHCIPCI</string>
11. <key>IOProviderMergeProperties</key>
12. <dict>
13. <key>kUSBMuxEnabled</key>
14. <true/>
15. <key>port-count</key>
16. <data>
17. AQAAAA==
18. </data>

```
19. <key>ports</key>
20. <dict>
21. <key>PRT1</key>
22. <dict>
23. <key>UsbConnector</key>
24. <integer>255</integer>
25. <key>port</key>
26. <data>
27. AQAAAA==
```

28. </data>

29. </dict>

30. </dict>

31. </dict>

Alles anzeigen

to get rid off the limitation just remove the port-count key and it's value and reinstall the kext.

---

### **Beitrag von „Sofista“ vom 27. April 2016, 05:22**

that application should I use to do this ...? It has some kext that enables all USB ports ...? there other ways to activate the USB ports on El Capitan 10.11.4 ...?

---

### **Beitrag von „Sofista“ vom 27. April 2016, 05:42**

other methods to enable all USB ports on El Capitan 10.11.4 ...?

---

### **Beitrag von „rubenszy“ vom 27. April 2016, 07:28**

put aDummyHDA.kext and AppleHDA.kext to S\L\E with Kext Utility  
copy the KextsToPatch from the config.plist to your clover config.plist  
put the DS DT.aml in the EFI\CLOVER\ACPI\patched folder and the USBInjectAll.kext in the

EFI\CLOVER\kexts\10.11 folder

remove all toleda appleHDA patch in your clover config

[GA- B75M -D3H.zip](#)

---

### **Beitrag von „Sofista“ vom 27. April 2016, 13:52**

I activated the sound of my hackintosh using the application MAC POISON EL CAPITAN .... have 8 USB ports on my Hackintosh and only 2 USB ports are not enabled .... just want to activate the 2 USB ports that have not been activated. ... I'm from Brazil ... I would have to explain to me using picture of how to enable the USB ports ....?

---

### **Beitrag von „al6042“ vom 30. April 2016, 12:22**

Since you are not native english speaker and it would be a major issue to prepare any explanation in english, I would like you to take a look at the forums with native english speaking audiences.

And btw. Mac Poison is part of the already mentioned and not allowed [Distros](#)... so please use the next 14 days to think about what stuff you gonna post in here.