

Hackintosh NUC random reboots (Catalina 10.15.2/6)

Beitrag von „yogitea“ vom 16. Juli 2020, 20:09

Hallo.

Hat jemand ne Idee, wie ich herausfinde, wieso mein NUC8i5 Catalina 10.15.6 (und davor 10.15.2) immer mal durchstartet?

Habe alle empfohlenen Kext für den NUC drauf. Auch in der neuesten Version. Clover auch neueste Version.

Mir wäre auch geholfen, wenn mir jemand sagen könnte wo ich eventuell die Absturzlogs finde. Da der NUC als "Server" in der Ecke steht bekomme ich das ja meistens nur durch Zufall mit, wenn es passiert.

Vielen Dank.

Kext Updater Ausgabe

Checking AirportBrcmFixup ...

You are up to date (2.0.7)

Checking AppleALC ...

You are up to date (1.5.0)

Checking BrcmPatchRam ...

You are up to date (2.5.3)

Checking Clover ...

You are up to date (5119)

Checking CodecCommander ...

You are up to date (2.7.1)

Checking FakePCIID ...

You are up to date (1.3.15)

Checking FakeSMC ...

You are up to date (1800)

Checking IntelBluetoothFirmware ...

You are up to date (1.1.1)

Checking IntelMausi ...

You are up to date (1.0.3)

Checking Lilu ...

You are up to date (1.4.5)

Checking USBInjectAll ...

You are up to date (0.7.5)

Checking WhateverGreen ...

You are up to date (1.4.0)
