

Audio issus on Catalina

Beitrag von „a809281944“ vom 6. Oktober 2020, 10:49

about my machine:

Process:i3-7100

Graphics:HD 630

Main Board:B250ET2

Audio:ALC 891

Ethernet:RTL 8111

BootLoader:OC 0.6.1


macOS Version:10.15.6

any can help me fix audio problem ,I tried Use Latest AppleALC.kext and Lilu.kext ,add alcid=11,13,15 in config.plist,But no Lucky.

Beitrag von „karacho“ vom 6. Oktober 2020, 12:20

Your Biostar Mainboard has ALC887, not ALC891 ->
<https://motherboarddb.com/motherboards/554/>

Try another layout-id -> <https://github.com/acidanthera...alc/wiki/supported-codecs>



Beitrag von „a809281944“ vom 6. Oktober 2020, 14:09

yes, I got this information from ubuntu, also I tried AppleALC887 and 891 Support Codec, No work; Before 10.13.6 all of the devices work, including Ethernet Audio Display Sleep Why Updated 10.15.6 without Audio

Beitrag von „karacho“ vom 6. Oktober 2020, 18:14

I suggest, you open current Hackintool, above click PCI and below the Export Icon. After this you'll find some generated files. One of them is PciDevices.plist. Load this file and your current config.plist with PlistEdit Pro. In PciDevices.plist expand the device tree to find the PCI Address of your Audio Device, drag&drop this tree into your already opened config.plist to DeviceProperties->Add. Make sure not to paste it into an already existing Device tree. After this you can play and test with different alcids in bootargs.