

Can not boot after copy EFI to disk

Beitrag von „damquangvinh595“ vom 11. September 2021, 21:40

Hi everyone,

I installed MacOS Bigsur on my laptop. But after copy efi to disk, i can't boot and stop here (photo). Please help me fix this error.

Thank you!!!

My specs:

HP Spectre X360(8 gen core)

- Processor & Memory: Intel, [Core i5](#) , Core i5-8265U, 3.90 GHz, 8 GB RAM
- Operating System and Software Included:[Windows 10 Pro](#) Operating System, Microsoft Office 365, Windows 10 Pro Included
- Storage: [Flash Memory Solid State](#) , 256.0 SSD
- Display: 13.3 inches, [LED display](#), [1920 x 1080 \(Full HD\)](#)
- Ports & Connectivity: 1 USB 3.0 Ports, 0 USB 2.0 Ports, Bluetooth
- General Information: [Integrated Graphics Type](#),[Intel UHD Graphics 620](#)

Beitrag von „Raptortosh“ vom 11. September 2021, 21:44

Hi and welcome!

Which Hardware and Bootloader do you use?

Beitrag von „damquangvinh595“ vom 11. September 2021, 21:48

Hi, my CPU is i5-8265U and I'm using Clover. I tried use clover and opencore but i can't boot after copy efi to disk.

Beitrag von „Raptortosh“ vom 11. September 2021, 21:53

Use opencore if you already have an Efi with it.

[BIOS settings?](#) Efi works from USB?

Beitrag von „damquangvinh595“ vom 12. September 2021, 03:53

Opencore and clover working when i boot from USB.

Beitrag von „bluebyte“ vom 12. September 2021, 06:18

You are using Mac OS and Windows as Dual-Boot-System on the same disk? This isn't a good idea, because you can get some Boot-Problems.

It's much more better, when you install every system on a separate disk. Show a Screenshot of your partitions and volumes.