

Update Big Sur Hacintosh zu Monterey hängt sich direkt zu begin auf

Beitrag von „Leandro2427“ vom 16. August 2022, 17:25

Hallo,

Ich bin über jede Hilfe Dankbar, nachdem Ich es seit fast drei Wochen versuche ohne hilfe zu löse hoffe Ich das einer con euch mir helfen kann!

Das problem ist folgendes:

Mein Hacintosh lief reibungslos auf MacOS Big Sur, ich würde ihn aber gerne zu Monterey Updaten.

Also habe ich Die Config.plist, die Kernel replace Werte der patche, sowie die kexte für das Update angepasst. Doch ich scheitert nun schon direkt zu begin.

Ich stelle gerne alles zur Verfügung, sagt einfach was ihr zur Analyse benötigt

. Ich Hänge das Bild des Outputs beim booten an.

Schonmal im Voraus vielen vielen Dank!

Beitrag von „fabiosun“ vom 16. August 2022, 17:33

Hello

post your config . plist

or try to see if you have enabled ProovideCurrentCPUinfo after updating your OpenCore boot loader and AMD KernelPatches

Beitrag von „Leandro2427“ vom 16. August 2022, 17:35

This is my config.plist

Beitrag von „fabiosun“ vom 16. August 2022, 17:38

Do you know which version of OpenCore are you using?

Here I see old AMD Kernel Patches

attached your config updated in it only Kernel Patches for your CPU in left profile AMD 2600

Beitrag von „Leandro2427“ vom 16. August 2022, 17:40

It

should be OC 8.2, I updated it and Hackintool also shows that it worked

Beitrag von „fabiosun“ vom 16. August 2022, 17:43

For Monterey that version is fine, if you like try to use config.plist I have posted above and see if you pass that hang you have (it should if your config was working properly in BigSur)

Beitrag von „Leandro2427“ vom 16. August 2022, 17:43

If it is allowed I can post my the two complete EFIs, the one before I tried updating and the one after my unsuccessful attempt

Beitrag von „fabiosun“ vom 16. August 2022, 17:44

[Zitat von Leandro2427](#)

If it is allowed I can post my the two complete EFIs, the one before I tried updating and the one after my unsuccessful attempt

it is useful IMHO only the one working in BigSur

Beitrag von „Leandro2427“ vom 16. August 2022, 17:45

This one was working perfectly

What do you mean by your config.plist being posted above?

Beitrag von „fabiosun“ vom 16. August 2022, 17:51

This is your previous EFI updated with new kernel patches and kernel

if you like, try and post your results

Beitrag von „Leandro2427“ vom 16. August 2022, 17:53

It takes around 50 min to see the result, or is there a workaround?

Beitrag von „fabiosun“ vom 16. August 2022, 17:55

[Zitat von Leandro2427](#)

What do you mean by your config.plist being posted above?

I have posted in a previous message a config.plist updated for your old 082 config posted

[Zitat von Leandro2427](#)

It takes around 50 min to see the result, or is there a workaround?

? sorry I do not understand

Beitrag von „Leandro2427“ vom 16. August 2022, 18:11

I press Update to monterey - then an Installation happens- After around 50 min it reboots and previously the error occurred

Beitrag von „fabiosun“ vom 16. August 2022, 18:13

if you did the first installation part, you can change with my EFI and reset Nvram
then go on with macOS installer icon you should have in your boot menu

Beitrag von „Leandro2427“ vom 16. August 2022, 19:17

Oh, thank u, i ll try

After pressing the installer item it did do a lot of stuff and then returned to the OpenCoremenu, So there is probably something else that Needs to be changed

Beitrag von „fabiosun“ vom 16. August 2022, 19:24

[Zitat von Leandro2427](#)

After pressing the installer item it did do a lot of stuff and then returned to the OpenCore menu, So there is probably something else that Needs to be changed

this should be a normal step

you have to relaunch again macOs installer icon, if you have, for a couple of time, then you should see normal OSX icon to go on in latest installation steps

Usually it reboots for about 4 times

Beitrag von „Leandro2427“ vom 16. August 2022, 20:21

Ok, I'll keep u updated

After rebooting for at least 15 times nothing happend☹

Beitrag von „fabiosun“ vom 16. August 2022, 20:39

To install max 4/5 reboot after first step done updating in OS X

Do you see a kernel panic before reboot?

Beitrag von „Leandro2427“ vom 16. August 2022, 20:43

No, or if you want I can try filming it and
Then post a screenshot of the last output

Beitrag von „fabiosun“ vom 16. August 2022, 20:54

With this efi Big Sur start?
I mean this updated one

Beitrag von „Leandro2427“ vom 16. August 2022, 21:06

Yes it did start

After re  was in prior, but now I am stuck on this

screen:

Beitrag von „fabiosun“ vom 16. August 2022, 22:22

[Leandro2427](#) check if you have declared this kext in your efi and config.plist

AppleMCEReporterDisabler.kext

If not

Declare in kernel/add and copy in OC/kext

Beitrag von „Leandro2427“ vom 16. August 2022, 23:00

I had in the newer version, but not in the one edited by you☐☐

I'll add it and then post the result 😊

It worked, MacOS Monterey is running☐☐☐☐☐

Thank you so much!