

# Der Mauszeiger (USB) bewegt sich ruckelnd

Beitrag von „commonworking“ vom 2. Mai 2024, 08:58

Hallo zusammen.

Meine Hardware (m / b DFI-SD106-Q170, CPU - i3-7300, iGPU - HD 630). Bootloader OC 0.9.9.  
Mac OS 13.6.6

Nach 5 Sekunden bewegt sich der Mauszeiger ruckartig. Nach 10-15 Sekunden verschwindet das Problem. Das Gleiche passiert im Mac OS-Installationsmenü. Dieses Problem ist kürzlich aufgetreten.

- geolokalisierung ist deaktiviert;
- OC und kexts aktualisiert;
- gebrauchter USB-Anschluss.kext und xhciportlimit - false;
- gebrauchte USBInjectAll.kext und xhciportlimit - wahr;
- Ich habe versucht, eine andere Maus zu wechseln;

- verwendete verschiedene USB-Anschlüsse;
- alles vom Motherboard entfernt, außer CPU-Speicher SSD und Maus;
- ausführen von MacOS 13.6.5 (auf einer anderen SSD);
- nur beim Starten von MacOS über Clover gibt es keine Cursorsrucke. Und es gibt keine Idioten in Windows.

Was könnte das Problem sein?

---

### **Beitrag von „Wolfe“ vom 2. Mai 2024, 09:37**

Wireless mouse? Reset bluetooth.

indexing agent at work? Wait it out.

---

### **Beitrag von „commonworking“ vom 2. Mai 2024, 10:45**

#### [Zitat von Wolfe](#)

Wireless mouse? Reset bluetooth.

indexing agent at work? Wait it out.

Hi.

The USB mouse is wired.

Do you mean spotlight?

---

### **Beitrag von „Wolfe“ vom 2. Mai 2024, 10:59**

Spotlight might overwhelm your cpu temporarily, yes. But this should be all the same with clover.

---

### **Beitrag von „apfel-baum“ vom 2. Mai 2024, 12:05**

[commonworking](#)

does your graphic hardwareaccelaration work- are the usbports correct mapped?

lg 😊

---

### **Beitrag von „commonworking“ vom 2. Mai 2024, 14:21**

[Zitat von Wolfe](#)

Spotlight might overwhelm your cpu temporarily, yes. But this should be all the same with clover.

Unfortunately, disabling spotlight did not give results.

Perhaps because Clover is not fully configured.

---

### **Beitrag von „commonworking“ vom 6. Mai 2024, 07:45**

[Zitat von apfel-baum](#)

[commonworking](#)

does your graphic hardwareaccelaration work- are the usbports correct mapped?

Ig 😊

The built-in HD630 video is used here. (foto 1)

The video starts normally.

I've tried two options: (foto 2)

- used usbport.kext and xhciportlimit - false;
- used USBInjectAll.kext and xhciportlimit - true;

The result is the same.

The most incomprehensible thing is why this happens in the Mac os installation menu. This problem has appeared recently.

---

### **Beitrag von „apfel-baum“ vom 6. Mai 2024, 07:48**

is it a install to an harddisk or ssd?

Ig 😊

---

### **Beitrag von „commonworking“ vom 6. Mai 2024, 10:59**

[Zitat von apfel-baum](#)

is it a install to an harddisk or ssd?

lg 😊

SSD

---

### Beitrag von „apfel-baum“ vom 6. Mai 2024, 11:06

what about ram? 4, 8 ,16gb?

lg 😊

--

edit-

have you already done a nvram reset?

---

### Beitrag von „commonworking“ vom 6. Mai 2024, 11:18

[Zitat von apfel-baum](#)

what about ram? 4, 8 ,16gb?

lg 😊

*have you already done a nvram reset?*

8 Gb DDR4 2133

I do this periodically, especially after significant operations (reset).

---

### **Beitrag von „Wolfe“ vom 6. Mai 2024, 14:48**

Ram might just be the culprit. 8Gb were good enough for Leopard but Sonoma is a different story. Maybe there's a cheap way of giving it a shot with 16gb buried somewhere in a drawer?

---

### **Beitrag von „commonworking“ vom 6. Mai 2024, 15:20**

#### [Zitat von Wolfe](#)

Ram might just be the culprit. 8Gb were good enough for Leopard but Sonoma is a different story. Maybe there's a cheap way of giving it a shot with 16gb buried somewhere in a drawer?

I will try to use another module. But I only have Ventura. And unfortunately I don't have a table where 16 GB can be hidden.

There is no such problem in Windows.

---

### **Beitrag von „Wolfe“ vom 6. Mai 2024, 15:47**

Don't throw money at it yet on the off-chance of ram issues. Anyone have an idea?

---

### **Beitrag von „commonworking“ vom 7. Mai 2024, 08:24**

### [Zitat von Wolfe](#)

Don't throw money at it yet on the off-chance of ram issues. Anyone have an idea?

Replacing another RAM module did not give any results.

---

### **Beitrag von „apfel-baum“ vom 7. Mai 2024, 13:06**

in twice, change your hardwaresetup take a look at the hardwarecenter -> [Hardware Center](#) or stay with clover, your version of osx and /or look for the manual <https://github.com/5T33Z0/Clover-Crate> for example.

for newer clover version-configuration setup

lg 😊